



Analog Transmitter

MAT 4191 with software extension

- analog evaluation signal
- Display of % / mA / Pulses
- Analog output 4 – 20 mA
- Limit value with Relayoutput
- for Impedance Measurement
- Drift memory
- Dynamic limit value

- MAT-Version V1.1x
- Technical specifications
- Operating
- Commissioning
- Installation

mipromex[®]
for monitoring product
measurements



Sales: **Aquasant Measuring Technique Ltd**

Manufacturer:

Hauptstrasse 22

CH - 4416 Bubendorf / Switzerland

☎ +41 (0)61 935 5000

📠 +41 (0)61 931 2777

✉ info@aquasant-mt.com

💻 www.aquasant-mt.com

Manual No.: VEB-Mipromex-MAT4191-V1.1x_ATEX09.docx

Version: V11503/3

Pages: 45

Author: R. Inauen

Modifications: Subject to modifications

Dear Customer

Congratulations! With this system you have chosen a high performance unit of the famous **mipromex®** line from **Aquasant-mt Switzerland**. The analog transmitter **MAT** for one or two measuring circuits changes the normed impedance measuring signal of a pipe- or bar-probe into a 4 - 20 mA signal.

Reading and carefully following the operating instructions, assures a perfect functioning of your **MAT** system.

There's something else which is important for you to know:

If any troubles should appear (opposite all our expectations), then our

Aquasant-mt Switzerland service department will assist you even long time after you purchased your **MAT Analog transmitter**.

Using this manual

Symbols and conventions

- In this document the following conventions are used at formatting to differentiate text elements.
- The names of equipment pieces are written in **BOLD**.
Example: **mipromex®**

In this document the following terms and symbols are used for special program messages:

Emphasized symbols and notices and their meaning:





















| | | | |
|---|---|---|---|
|  | Mortal Danger: the non-observance can lead to injuries or death. |  | Step by step: Text enhanced/marked this way, contains detailed instructions and comments |
|  | Caution: the non-observance can lead to equipment damages or loss of information. |  | Actions to be carried out by user. |
|  | Information / Notice: describes equipment characteristic features. |  | Read and follow instruction steps. |
|  | A waiting time is required during which the equipment does recalibrate itself. |  | Compare with the mipromex® display. |
|  | Adjustment of the measuring electronic MTI (visualized by red and green LED's). |  | Plug in mains 230/115 V (24 V AC/DC). |
|  | Observe and control equipment display. |  | Send equipment back to manufacturer. |
|  | Button on mipromex® front panel |  | mipromex® Error message on display with Time/Date |
|  | Function: change value according to displayed character set |  | Button on mipromex® front panel |
|  | Change line without store |  | Function: select number or character |
|  | Button on mipromex® front panel, Function: back |  | Button on mipromex® front panel, Functions: menu, select, next, store (press more than 2s) |
| "next step" in navigation bar | press ok button on mipromex® . Press less than 2 seconds to advance to the next parameter | "store" in navigation bar | press ok button on mipromex® . Press more than 2 s to store |

Chart 1 Symbol description

Index

| | |
|---|-----------|
| 1. Security and precautions | 6 |
| 1.1. Installation | 6 |
| 1.2. Setup | 6 |
| 1.3. Hazardous Area protection | 6 |
| 1.3.1. Following notices must be observed: | 7 |
| 1.4. SIL Safety Integrity Level | 7 |
| 1.5. Cleaning of units | 7 |
| 1.6. Maintenance | 7 |
| 1.7. Warranty claims | 7 |
| 1.8. Waste disposal of electrical and mechanical components | 7 |
| 2. mipromex® type description | 8 |
| 2.1. MAT-Hardware types | 8 |
| 2.1.1. mipromex® type code: | 9 |
| 2.2. Software Versions | 10 |
| 2.2.1. Basic | 10 |
| 2.3. Basic functions | 11 |
| 2.4. Measuring circuit | 11 |
| 2.5. Function | 11 |
| 2.1. Measured values processing | 12 |
| 2.1.1. Static measure processing mode | 12 |
| 2.1.2. Dynamic measure processing mode | 12 |
| 3. Structure of data input (parameterization) | 13 |
| 3.1. General | 13 |
| 3.2. Key functions | 13 |
| 3.2.1. Input / changing of characters | 13 |
| 3.2.2. Select language | 13 |
| 3.3. Graphic display | 14 |
| 3.3.1. Display at switch-on of mipromex® | 14 |
| 3.3.2. Measured value display | 14 |
| 3.3.3. Menu parameter settings | 15 |
| 4. Program structure with parameters of the analog transmitter | 16 |
| 4.1. Description of the menu, program structure General, for all mipromex® units | 19 |
| 4.1.1. [1.] Basic settings | 19 |
| 4.1.2. [2.] Device specs | 22 |
| 4.1.3. [3.] Signal settings | 23 |
| 4.1.4. [5.] Measuring range | 25 |
| 4.1.5. [6.] Limit value | 25 |
| 4.1.6. [7.] Test functions | 27 |
| 4.1.7. [8.] Programmable mA output | 28 |
| 4.1.1. [12.] Calculation parameters | 28 |
| 5. Commissioning example | 30 |
| 5.1. Commissioning the mipromex® with a pipe probe | 30 |
| 5.1.1. Detection of water in petrochemical products | 30 |

| | | |
|-------------|--|-----------|
| 5.1.2. | Oil detection in process- or rain-water----- | 30 |
| 5.2. | Commissioning the mipromex® with a bar probe----- | 31 |
| 5.2.1. | Oil detection in process- or rain-water with float ----- | 31 |
| 5.2.2. | Foam detection ----- | 31 |
| 5.3. | Electronic calibration MTI, basic equalization ----- | 32 |
| 5.4. | Inspection release of the parameters ----- | 33 |
| 6. | Fault finding ----- | 35 |
| 6.1. | After power on ----- | 35 |
| 6.2. | During operation----- | 35 |
| 6.2.1. | Data error ----- | 35 |
| 6.2.2. | Display error ----- | 37 |
| 6.2.3. | Radio equipment ----- | 37 |
| 7. | Wiring diagram ----- | 38 |
| 7.1. | Measuring electronic/probe with fix connection ----- | 38 |
| 7.2. | Connections to female multipoint connector with 32 poles, type: MAT 4190 ----- | 39 |
| 7.3. | Printed circuit board for 19"-Rack, Monorack, Wall- and Table Top housing ----- | 40 |
| 7.4. | Earthing of microprocessor units and probes ----- | 41 |
| 8. | Technical Data ----- | 42 |
| 8.1. | mipromex® Analog transmitter type: MAT 419x ----- | 42 |
| 8.2. | Measuring electronic MTI for measuring probes ----- | 43 |
| 8.2.1. | Technical Data MTI . . . / .----- | 44 |

1. Security and precautions

The following points must be considered at installation and setting up of microprocessor units 24 V AC/DC of Treina Electronics AG:

1.1. Installation

- ∫ The units are IP20 according to EN 60529 and must be protected against e.g. splash water or pollution exceeding the degree of pollution 2.
- ∫ The units must be installed outside the hazardous area.
Maximum 7 units can be installed into a 19"-Rack. Multipoint connector type: FI32 must only be equipped with d- and z – contacts. Solder connections are to be isolated with heat shrinkable sleeves (see chapter 7.2)
- ∫ Single units installed with Monorack Type: MRM 2 (see chapter 7.4)
Housings or switch cabinets must be ventilated (dissipation of heat built-up)
- ∫ Hazardous area blue line to lead separately (cable channel or joined to loom of cables)
Equipotential bond must be installed; Hazardous area protection
Outside installations: a corresponding lightning protection of the probe supply cables is recommended.
- ∫ Installation instructions for impedance probes I must be observed

1.2. Setup

- ∫ Verify wiring and power supply tension (chapter 7.2)
- ∫ Perform probe and system specific parameterization in the menu (chapter 5)
- ∫ Check max. load of the opto-electronic coupling transistor outputs (NPN) according to datasheet (chapter 7.6)
- ∫ Adjustments under tension are only allowed to be carried out by manufacturer
Handling by user is performed only via protected film keypad
Repair of unit only by trained personnel with manufacturer certificate

1.3. Hazardous Area protection

The EC-type examination certificate has to be respected. It is specially important to respect the contained "special conditions". Ex certification according to Directive 94/9/CE (ATEX 100 A).

Confidential test certificate no. 08-IK-0396.01 **CE 1254**
EC-type examination certificate SEV09 ATEX 0132

| | |
|---------------------------|--|
| Notification no.: | QS 11 ATEX 2081  |
| Ex classification: | II (2)G [Ex ia] IIC II (2)D [Ex iaD] II (2)GD |

Please pay attention to the following documents:

- **VEZ-SEV-ATEX-09-ISO_Certifcat-Doc.pdf** (actually valid certificats)
- **VED-TSS**....**probe data sheet with specific (X) Ex-relevant coat thicknesses and information regarding the application in which zone
- **08-IK-0396.01** the test certificate with the characteristics is submitted in strict confidence.

1.3.1. Following notices must be observed:

1. The microprocessor control unit **mipromex®** as per EN 60079-0:2006 can only be used outside of the hazardous area.
2. The highest allowed ambient temperature is 60°C (also inside a protective housing)
3. The microprocessor unit **mipromex®** is to install in a manner that at least the protection standard IP 20 as per Standard IEC 529 resp. EN 60529 is fulfilled. By corresponding mount into rack unit this condition is fulfilled.
4. At installation of the microprocessor control unit **mipromex®** a minimum distance of 50mm must be created by insertion of a separation wall between the intrinsic safe and non intrinsic safe wiring circuit or the connecting parts must be insulated (i.e. with a heat-shrinkable sleeve). The input lines are secured to the rack or the monorack with a strain relief.
5. The intrinsic safe signal wiring circuits are safe galvanic separated from the remaining wiring circuits up to a peak value of 375 V of the nominal voltage

1.4. SIL Safety Integrity Level

The microprocessor unit **mipromex®** is produced as per the SIL standards Norm IEC 61508/61511.

1.5. Cleaning of units

The microprocessor unit **mipromex®** and the measuring electronic **MTI** built-in on the probe head are not allowed to be cleaned with water.

The cleaning of the front panel is to be done with a slightly damped, clean cloth. The printed circuit boards, to remove the dust, shall only be slightly blown-out with compressed air (low pressure 4 bar).

The bar probes must be cleaned with alcohol or a corresponding solvent.

Probes with stainless steel electrodes (SRK or SRM or probes made to measure powders/solids) are not allowed to be cleaned with water or liquids.

1.6. Maintenance

The data transmission of the microprocessor units remains stable, even over a long period of time. Therefore, a periodic adjustment or similar, is not necessary.

1.7. Warranty claims

Your measuring system had to undergo a precise final inspection at the factory. Interventions are only allowed to be carried out by a competent person. Warranty according to Aquasant Messtechnik AG warranty.

1.8. Waste disposal of electrical and mechanical components

The disposal of the components must be carried out in compliance with the country valid regulations.

2. mipromex® type description




Pic. 1 mipromex®

2.1. MAT-Hardware types

| | |
|---------------------|--|
| MAT 4190 | 1 measuring circuit with 1 analog output and 1 limit value output Relay |
| MAT 4110/220 | 2 measuring circuits with 1 analog outputs each (not potentially separated against each other) and 1 limit value output OC each. The second measuring circuit can be activated with an activation code subject to costs. |
| MAT 4220 | 2 measuring circuits with 1 analog output each (not potentially separated against each other)* |
| MAT 4240 | 2 measuring circuits with 1 analog output each (potentially separated against each other)* |

*) no change in software except type code)

2.1.1. mipromex® type code:



X₁ M = mipromex®

X₂ A = Analog I = Interface
L = Level P = Product

X₃ L = Limit/Level M = Monitoring T = Transmitter
R = Recognition Q = Quality S = Switch
L = Level U = Universal

X₄ 1 = Limit switch 4 = Analog output 7 =
2 = Level switch empty 5 = Universal new 8 = Interfacial layer
3 = Level switch full 6 = Filling level 9 = Product (quality, type, concentration)

| X ₅ | Meas. print | MeV of 2nd. unit | analog input | digital input |
|----------------|-------------|------------------|--------------|---------------|
| 1 | 1 | | | 3 |
| 2 | 2 | | | 3 |
| 3 | 2 | 1 MeV ex Rackbus | | 3 |
| 4 | 2 | 2 MeV ex Rackbus | | 3 |
| 5 | 1 | | 1 | 3 |
| 6 | 2 | | 1 | 3 |

| X ₆ | relay | OC | analog output | DC-converter |
|----------------|----------|----|---------------|--------------|
| 0 | 2 | | | |
| 1 | | 1 | 1 | 1 |
| 2 | | 2 | 2 | 1 |
| 3 | 2 | | 1 | 1 |
| 4 | | 2 | 2 | 2 |
| 5 | 2 | | 2 | 2 |
| 6 | 2 | | 2 | 1 |
| 7 | | 2 | | |
| 8 | 2 intern | | 1 | 1 |
| 9 | 1 | | 1 | 1 |

One DC-converter, with potential separation, analog output toward power supply
Two DC-converter, additional potential separation, analog outputs toward each other

X₇ 0 = standard - software
1 = first expansion of a standard - software

X₈ - = without
C = controller (device with control function) e.g. **MIL 8110 C** interfacial layer level controller
P = product compensation
S = Segment

Ex Ex = with hazardous area protection according to ATEX II(2)G [Ex ia] IIC // II(2)D [Ex iaD]
Exd = with hazardous area protection according to ATEX II(2)GD [Ex d ia] IIC
NEx = without hazardous area protection on measuring print

2.2. Software Versions

2.2.1. Basic

The standard operating software is used for all basic hardware units. The basic functions are identical for all software versions; you can use them on all the units. Software versions are marked according to NAMUR EN53.

Example:

| | | |
|---------------------|-------|--|
| MAT 4190 | V1.1x | 1 measuring circuit with one analog output and one Relay limit value |
| MAT 4110/220 | V1.1x | 2 measuring circuits with 1 analog outputs each (not potentially separated against each other) and 1 limit value output OC each. The second measuring circuit can be activated with an activation code subject to costs. |
| MAT 4220 | V1.1x | 2 measuring circuits with one analog output each and one limit value each* |
| MAT 4240 | V1.1x | 2 measuring circuits with one analog output each (potentially separated against each other) and one limit value each* |

(* no change in software except type code)

Within each software type, at cost, additional functions can be activated.

For each additional function a separate activation code is generated for each measuring circuit. The activation code is serial number depending.

Examples for additional functions:

- Second measuring circuit for **MAT 4110/4220**

The simple menu navigation (language selectable) assures a fast and accurate operation.

Input can be made via buttons and display of the device or via connection to a laptop or the process control system.

2.3. Basic functions

The **mipromex® MAT** has one or two separated and independent measuring circuits. Depending on the device type, one or two measured signal processing can be activated.

The pulse signal transmitted by the measuring electronic MTI is transformed into an offset compensated and filtrated pulse value and converted into a 4 – 20 mA signal in function of the selected measuring span.

The output signal is displayed as pulses value, % value or as mA value.

The offset range can be set between 10 and 2000 pulses.

The measuring signal offset (zero point) can be picked up automatically and/or the stored value can be modified via the keypad buttons. The measuring span is product dependent determined and automatically stored and/or the stored value can also be modified manually via the keypad buttons.

The pulses signal is converted into a 0 – 100 %-value.

The 4 - 20 mA analog output can be spread via programmable start and end values.

Parameter input is menu-driven and device-type based. Inactive positions are hidden.

The parameters can be stored and reloaded.

For each measuring circuit, an opto-electronic coupler transistor output (OC) with Low and Hi function as well as an adjustable time delay for drop and activation is at disposal. Fault messages are visualized with time and date of the error.

2.4. Measuring circuit

One or two probes with the measuring electronic MTI in the connecting head are connected to the **mipromex® MAT** using a shielded two core cable. Between field and control room an equipotential bond must be installed.

2.5. Function

A product surrounding or filling an Aquasant-mt impedance pipe or bar probe you varied the impedance in function of the dielectrical constant and/or conductivity characteristics of organic products or aqueous solutions as, well as the immersion depth of the active part of the bar probe .

The measured impedance sum signal is converted directly by the measuring electronic MTI into a normed signal and is transmitted as pulse packages to the analog transmitter **mipromex® MAT**.

The measured values within the normed signal range are product specific and characteristic for the different products and changing in accordance with product mixtures or immersion depth - This product specific measured value correspond to a value in the range of 0 – 3700. The physical impedance measured value of a product is registered in digits, designed as pulses value.

In a measuring electronic range (e.g. MTI 100) the dielectrical value of 100 pF is converted into a range of 0 – 3500 pulses.

A modern and menu driven operation and calibration concept enables a time saving commissioning of the analog transmitter. The frontal key pad with function and graphic display assure a user friendly operation and reliable working.


Use for foam and powder surveillance, recognition of water in petrochemical products or organic products in water or surveillance of surface oil layers with floater probes

2.1. Measured values processing

The safety level switch MLS is equipped with 2 different measured values processing modes: **stat** and **dyn**. The factory setting at delivery or after initialization is the **stat** (static) process mode.

| Pos.-Nr. | settings | description |
|----------|-----------------|--------------------------------|
| 6.1.2 | stat/dyn | Static measure processing mode |
| 6.1.7 | FSL/ FSH | Safety level (full) switch |
| | | |


2.1.1. Static measure processing mode



Pic. 2 static measure processing mode

2.1.2. Dynamic measure processing mode

| Nr. | settings | description |
|--------|-----------------|-------------------------------------|
| 6.1.2. | stat/dyn | Dynamic measure processing mode |
| 6.1.3. | 3000 Imp | Max. limit value (as example below) |
| 6.1.4. | 50 Imp | Hysteresis (as example below) |
| 6.1.5. | 00.02 mm.ss | Relay Time delay, drop |
| 6.1.6. | 00.00 mm.ss | Relay Time delay, tension |
| 6.1.7. | FSL/ FSH | Safety level (full) switch |



Pic. 3 dynamic processing mode

3. Structure of data input (parameterization)

3.1. General

To select a menu point or to go forward/ "next" step in the menu, use the **OK** button.

The function of the **OK** button is shown in the inversed bar at the bottom of the display.

The position number of the actual menu item is displayed at bottom left.

To select the desired menu item use the **▲ ▼** buttons. The selected menu item is shown inversed. To execute the shown function use the **ok** button, to delete a value or go back to the previous menu, use the **C** button.

3.2. Key functions

| Key | description | Messwert-Anzeige | in main menu | menu line | Data input |
|-----------|--------------------------------|------------------------------|------------------|-------------|-------------------------------------|
| ▲ | up | Advancing display | "next" menu item | 1 step up | 0 – 9 / A - Z |
| ▼ | down | next dysplai | "next" menu item | 1 step down | 0 - 9 / A - Z |
| ▶ | right | - | no function | no function | input right |
| ◀ | left | - | no function | no function | input left |
| OK | "next" / menu / select / store | (>2 s) Confirmation error | select | confirm | forward or (>2 s) store and forward |
| C | back | retour | back | back | back |

Chart 2 Key functions

3.2.1. Input / changing of characters

Every parameter has its own input field.

The input and change of parameter values can be done using the **mipromex®** menu or via PC-Software.

For several menu configuration text input is required. Text input is done the same way in all functions.

Input via buttons on the **mipromex®** key pad is done as follows:

The first position, beginning on the left, is inverted. To change the character use the **▲ ▼** buttons.

To select the next position use the **◀ ▶** buttons.

With the **ok** button (press >2 sec) the new value is stored and the display changes to the next parameter.

You can reactivate the old value using the **C** button. If no input is made during an adjustable amount of time, the display changes back to measured value.




Chart 3 Display

3.2.2. Select language

The languages Deutsch/English/Français are available and selectable in the **mipromex®** menu. A fourth language can be programmed. The parameter text field is loaded according to language code via PC-Software. Changes of the text can not be done using only the microprocessor unit **mipromex®**!




3.3. Graphic display

The format of the display is as follows:

Every menu position, parameter and device unit can be set active or inactive (not visible) according to the function of the device. The display is also adjusted to the function of the device.

3.3.1. Display at switch-on of mipromex®

| | |
|--------------------------------|---|
| Vendor |  |
| Name of device generation | mipromex® |
| ok button function | Next |
| | ok: forward to device type |
| Unit description | Analog transmitter |
| Device type and hardware model | Device type |
| | MAT 4190 |
| ok button function | Next |
| | ok: forward to meas.value display |

3.3.2. Measured value display

Unit type (with 1 measuring circuit) **MLS 1100, MAT 4190, MLT 6130, MIQ 8130, MIL 8110**

| | |
|--|--------------------------------|
| Description of the 1. measuring position | 1 Pos. QLA12345 678 |
| Description of the (1 st) measured value | Analog output 1 |
| Actual calibrated meas.value display in % | 100.0 % Hi |
| Change and input in Menu 5.1.2 | Menu ▲ ▼ |
| ok button function / active keys | ok: change back to menu |

Change and input in measuring circuit 1, Menu 3.1.1.

Limit value "Hi" (high) is reached

Change and input in measuring circuit 1, Menu 6.1.2

▲ ▼ : circulate (loop) in display mode

Pos. no. can be entered in the menu

Unit types with 2 measuring circuits: **MLS 1200, MAT 4220/4240, MLT 6250, MIL 8240**

| | |
|---|--------------------------------|
| Description of the 2 nd measuring position | 2 Pos. QLA12345 679 |
| Description of the 2 nd measured value | Analog output 2 |
| Actual calibrated meas.value display in % | 100.0 % Hi |
| Change and input in Menu 5.1.2. | Menu ▲ ▼ |
| ok button function / active keys | ok: change back to menu |

Change and input in measuring circuit 2, Menu 3.1.1.

Limit value "Hi" (high) is reached

Change and input in measuring circuit 2, Menu 6.1.2

▲ ▼ : circulate (loop) in display mode

| | |
|---|--------------------------------|
| Description of the outputs | Analog outputs |
| Display of the 1 st and 2 nd measured value | 1 100.0 % |
| Actual calibrated meas. value display in % | 2 100.0 % |
| Change and input in Menu 5.1.2. | Menu ▲ ▼ |
| ok button function / active keys | ok: change back to menu |

▲ ▼ : circulate (loop) in display mode

In case of alarm sign ▲, "Lo" or "Hi" : no display of impulse or % values/digits

| | |
|---|--------------------------------|
| Description of the outputs | Analog outputs |
| Display of the 1 st and 2 nd measured value | 1 20.00 mA |
| Display of actual current output values | 2 20.00 mA |
| ok button function / active keys | Menu ▲ ▼ |
| | ok: change back to menu |

▲ ▼ : circulate (loop) in display mode (loop)

Description of the 1st measuring position
Display of the measured value
Actual calibrated meas.value display in %
measured value display in pulses

ok button function / active keys

1 Pos. QLA12345 678
100.0 %
3750 Imp
Menu ▲▼

ok: change back to menu

Change and input in Menu 3.1.1.

▲▼: circulate (loop) in display mode

Description of the 2nd measuring position
Display of the measured value
Actual calibrated meas.value display in %
measured value display in pulses

ok button function / active keys

2 Pos. QLA12345 679
100.0 %
3750 Imp
Menu ▲▼

ok: change back to menu

Change and input in Menu 3.1.1.

▲▼: circulate (loop) in display mode

3.3.3. Menu parameter settings

After pressing the OK button the display changes to the info menu.

Menu-Information

Both functions of the **ok** button
store or
next

Menu Pos. No. / **ok** button function

=> Menu-Info <=
Press OK button
> 2s store !
< 2s next !
Info 01 **Next**

ok: change to password input

After pressing the OK button the display changes to the password input.

selected character is inverted

Menu Pos. No. / **ok** button function

Key in Password !
0000
▲▼◀▶ adjust
1. **Store**

ok: change to the menu

1. key-in the numerical password using the ▲▼◀▶-buttons

2. press **ok** button more than 2 seconds

Standard factory password 0000

Display changes to the menu

Parameters can be changed

After pressing the OK button the display changes to the menu.

selected menu item is inverted














































Menu Pos. No./**ok** function/active keys

Basic settings
Device specs
Signal settings
Measuring range
1. **Select** ▲▼

ok: change to the selected menu item

▲▼: circulate (loop) menu items

4. Program structure with parameters of the analog transmitter

| Legend: | | | | | | | |
|---|--|-------|---|---|---|---|---|
|  = Select /  = Input /  = Display /  = only available with activation code | | | | | | | |
| Menu-Code Parameter | | Type: | MAT 4190 | MAT 4190/260 | MAT 4260 | MAT 4240 | Change |
| 1. Basic settings | | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 1.1. Language | | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 1.1.1. Deutsch | | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 1.1.2. English | | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 1.1.3. Français | | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 1.1.4. Free language / text | | | - | - | - | - |  |
| 1.2. Time/Date | | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 1.2.1. Time, input/correction | | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 1.2.2. Date, input/correction | | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 1.3. Modify Password | | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 1.3.1. Password input | | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 1.3.2. Modify password | | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 1.4. Lighting | | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 1.4.1. Lighting on/off | | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 1.4.2. Duration of lighting in min. / 0 = continuous ON | | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 1.5. Contact information | | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 1.5.1. Contact address | | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 1.5.2. Contact Tel./E-Mail | | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 1.5.3. Contact Web | | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 1.6. Factory settings | | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 1.6.1. Store parameter set | | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 1.6.2. Load parameter set | | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 1.6.3. Initialize device no/yes | | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 1.7. Activation code | | |  |  |  |  |  |
| 1.7.1. Activation of 2 nd measuring circuit, Code: ***** | | | - | <input checked="" type="checkbox"/> | - | - |  |
| 2. Device specs | | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 2.1. Device type: MAT 4190 or 4110/220 or 4220 or 4240 Software: Version V.... | | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 2.2. S/N and system verification date | | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 2.3. Quantity of measuring circuits (1 measuring circuit: skips 2.4.0/3.1.0/4.1.0) Battery type: CR2032 | | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 2.4. Select measuring circuit 1 or 2 | | | - | - | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 2.4.1. Type code probe 1 / 2 | | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 2.4.2. S/N 1 / 2 | | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 3. Signal settings | | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 3.1 Select measuring circuit 1 or 2 | | | - | - | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 3.1.1. Input position number / TAG number | | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 3.1.2. Probe factor | | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 3.1.3. Zero point input (Offset), accept at press of OK button, store | | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |

| Legend: | | Type: | MAT 4190 | MAT 4190/260 | MAT 4260 | MAT 4240 | Change |
|---|--|-------|---|---|---|---|---|
|  = Select /  = Input /  = Display /  = only available with activation code | | | | | | | |
| Menu-Code Parameter | | | | | | | |
| 3.1.4. Manual input of the zero point (Offset) | | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 3.1.5. Measuring span, accept at press button | | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 3.1.6. Height in percent at auto measuring span | | | - | - | - | - |  |
| 3.1.7. Measuring span input / correction manual | | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 3.1.8. Signal filter | | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 4. Commissioning according to device type | | | - | - | - | - |  |
| 4.1 Select measuring circuit 1 or 2 | | | - | - | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 5. Measuring range | | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 5.1 Select measuring circuit 1 or 2 | | | - | - | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 5.1.2. Measuring range starting point | | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 5.1.3. Measuring range end point | | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 6. Limit values | | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 6.1 Select measuring circuit 1 or 2 | | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 6.1.1. static/dynamic | | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 6.1.2. Limit value(s) | | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 6.1.3. Hysteresis /max. measured value | | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 6.1.4. Time delay, drop 1 | | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 6.1.5. Time delay, tension 1 | | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 6.1.6. FSL/FSH position | | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 6.1.7. Min./Max. measure value memory | | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 7. Test functions | | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 7.1. Select measuring circuit 1 or 2 | | | - | - | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 7.1.1. mA- output simulation (0.1 mA steps) beginning at 0.5 mA | | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 8. Error message mA output | | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 8.1. Data error, measured value underflow, <0010 pulses | | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 8.2. Data error, measured value overflow, >3750 pulses | | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 8.3. Technical error | | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| Display actual error with time/date | | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 9. Controller function | | | - | - | - | - |  |
| 10. Protocol of active data set | | |  |  |  |  |  |
| | | | | | | | |
| 11. Service parameter basic settings | | | - | - | - | - |  |
| 11.1. Service parameter list (encoded) | | | - | - | - | - | PC |
| 11.2. Parameter list for different device types | | |  |  |  |  | |
| 12. Calculation parameters | | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 12.1. Select measuring circuit 1 or 2 | | | - | - | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 12.1.1 Drift memory | | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 12.1.2 Drift gradient | | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 13. Archive | | |  |  |  |  |  |
| 13.1. Operation parameter sets (last set of parameters) | | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |

Legend:

 = Select /
  = Input /
  = Display /

 = only available with activation code

Menu-Code Parameter
Type:
MAT 4190
MAT 4110/220
MAT 4220
MAT 4240
Change









| Display modes | | | | | |
|--|-------------------------------------|-------------------------------------|-------------------------------------|-------------------------------------|---|
| Analog output 1 in % | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| Analog output 2 in % | - | - | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| Analog output 1 in mA | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | - | - |  |
| Analog output 1/2 in % | - | - | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| Analog output 1/2 in mA | - | - | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 1. Pos. Number analog output 1 in % and measured value in pulses | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| 2. Pos. Number analog output 2 in % and measured value in pulses | - | - | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |
| Display actual error with time /date | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |  |

Chart 4 Program structure

4.1. Description of the menu, program structure General, for all mipromex® units



**mipromex®
display**



Your TAG or Position number
Measuring position, number
Display measured value in %
Hi = High Alarm

ok button function / active keys

1 Pos. QLA12345678
Analog output 1

100.0 % Hi

Menu ▲▼

After pressing the **ok** button the display changes to the info menu.

Information about storing or next

=> Menu-Info <=
Press OK button
>2s store !
< 2s next !

Info 01 Next

After pressing the **ok** button, the display changes to password input.

Password

The password protects the programming level of the **mipromex®**. If you start up for the first time, the standard password is **0000** and is displayed. If you change the password (under point 1.3.) every user has to log-in using the new password!

Note: If you loose the new password, contact aquasant-mt to obtain an override password.

Key in your new password or accept the standard password
selected digit is inverted

Key in Password !

0000

1. Store

1. Key-in the numerical password using the ▲▼◀▶ buttons
2. Press **ok** button more than 2 seconds

Display changes to the menu
Parameters can be changed

4.1.1. [1.] Basic settings

You can set the device specific parameters in the basic settings menu. Please note that you first have to activate the password before you can make any changes.

Main menu
selected menu item is inverted

Basic settings
Device specs
Signal settings
Measuring range
1. Select ▲▼

After pressing the **ok** button the display changes to the sub menu basic settings

Sub menu
Selected sub menu item is inverted

Language / Sprache
Time/Date
Modify password
Lighting settings
1.1. Select ▲▼

After pressing the **ok** button the display changes to the sub menu Language / Sprache

[1.1.] Language/Sprache

Select the desired language. After you selected the language and stored your choice, the new language will be activated immediately. On the internet homepage www.aquasant-mt.com / Downloads, you can download an Excel-file. The three languages Deutsch, English and Français are listed. Replenish all text blocks in your language (max 16-characters), send it to us and we will be glad to implement your language.

selected menu item is inverted

Deutsch
English
Français

1.1.1 Store ▲▼

1. select language with the ▲▼-buttons
2. press **ok** button more than 2 seconds

The selected language is immediately activated
Display changes back to menu item 1.1.

[1.2.] Time/Date

Correction of device time and date. The time is displayed in hours, minutes and seconds. Daylight saving time is not adjusted automatically! The date is displayed in day, month and year. The device time is used for the protocol logger.

| | | |
|--------------------------------|----------------------|---|
| current time | Time 09:50:25 | 1. use ▲▼◀▶-buttons to change the time |
| selected character is inverted | 09:50:14 | 2. press ok button more than 2 seconds |
| active key-navigation | ▲▼◀▶ Adjust | Time is stored |
| | 1.2.1 Store | Display changes to date 1.2.1. |

| | | |
|--------------------------------|----------------------|---|
| current date | Date 04.01.07 | 1. use ▲▼◀▶-buttons to change the date |
| selected character is inverted | 04.01.07 | 2. press ok button more than 2 seconds |
| active key-navigation | ▲▼◀▶ Adjust | Date is stored |
| | 1.2.1 Store | Display changes back to menu item 1.2. |

[1.3.1.] Key-in and change password

The **standard password (0000)** can be changed. The old password has to be confirmed first.

| | | |
|--------------------------------|-------------------------|---|
| selected character is inverted | Key in Password! | 1. use ▲▼◀▶-buttons to input the numerical password |
| | 0000 | 2. press ok button more than 2 seconds |
| | 1.3.1. Store | Password is stored |
| | | Display changes to modify password 1.3.2. |

[1.3.2.] Modify password

The standard password (0000) can be changed. The new password has not to be confirmed.

| | | |
|--------------------------------|-------------------------|---|
| selected character is inverted | Modify Password! | 1. use ▲▼◀▶-buttons to input the numerical password |
| | 5000 | 2. press ok button more than 2 seconds |
| | 1.3.2. Store | New password is stored |
| | | Display changes back to menu item 1.3. |

[1.4.1.] Lighting

The display lighting can be switched on or off. The duration of the lighting can be set in minute-steps; for continuously on choose time 00, under the menu point 1.4.2.!

| | | |
|--------------------------------|--------------------------|--|
| selected character is inverted | Lighting settings | 1. use ◀▶-buttons to switch the lighting on or off |
| | on/off | 2. press ok button more than 2 seconds |
| | 1.4.1. Store ▶▶ | Selection is stored |
| | | Display changes to sub menu lighting duration 1.4.2. |

[1.4.2.] Lighting settings

The display lighting can be switched on or off. The duration of the lighting can be set in minute-steps; for continuously on choose 00!

| | | |
|--------------------------------|--------------------------|---|
| selected character is inverted | Lighting settings | 1. use ▲▼◀▶-buttons to select the lighting duration |
| active key-navigation | 0 = continuous ON | 2. press ok button more than 2 seconds |
| | Time in min. 02 | Lighting duration is immediately activated |
| | ▲▼◀▶ Adjust | Display changes back to menu item 1.4. |
| | 1.4.2. Store | |

[1.5.] Contact

Our contact information: Address / Phone-No. / Email / Web

Aquasant-mt
measuring tech. Ltd
Hauptstrasse 22
CH-4416 Bubendorf
1.5.1. Next

After pressing the **ok** button the display changes to the next menu item.

/ **Switzerland**

Tel.:
+41(0)61 9355000
Email: info@
aquasant-mt.com
1.5.2. Next

After pressing the **ok** button the display changes to the next menu item.

/ **info@aquasant-mt.com**

Web: www.
aquasant-mt.com
1.5.3. Next

After pressing the **ok** button the display changes back to the sub menu Contact 1.5

/ www.aquasant-mt.com

[1.6.] Factory settings

Under the **Factory settings** Menu Level, the programmed device parameters can also be stored, reloaded or deleted. All parameters are set back to factory settings at initialization of the device.

[1.6.1.] Store Parameter set

All keyed-in parameters are stored in the flash memory of the unit. The parameters can be reloaded afterwards.

Store parameter
ok
1.6.1. Store

[1.6.2.] Load Parameter set

If parameters have been changed or deleted, the last flash stored parameter set can be reloaded into the RAM.

Load parameter
ok
1.6.2. confirm

[1.6.3.] Initialize unit no/yes

If the device is initialized, all user-programmed parameters are deleted and set back to factory settings.


Initialize unit
no/yes
1.6.3. confirm

[1.7.] Activation code

With the activation code, several optional dutiable **software packages/functions** can be activated. You can obtain the activation code by ordering the optional packages/functions (e.g. **MK 220** Article-No.: 02.05.03.0019). The activation code is *depending on the serial-number* and can not be used for other devices.


[1.7.1.] Activation of/for 2nd measuring circuit

On the Hardware type **MAT 4110/220** with one active measuring circuit, the second measuring circuit can be activated. If the code is entered incorrectly the menu jumps back to menu item 1.7. The code can be entered again! Once the second measuring circuit is activated, it can not be deactivated. At start-up the new hardware type **MAT 4220** will be displayed.

| | | |
|--|---|--|
| Description Code input active key-navigation |  | 1. use ▲▼◀▶-buttons to input the alpha-numerical Code 2. press ok button more than 2 seconds Input is stored Display changes back to menu 1. |
|--|---|--|

4.1.2. [2.] Device specs

In the device specs you will find specific information about the **mipromex®**.


| | | |
|---|---|--|
| Main menu selected menu item is inverted |  | After pressing the ok button the display changes to the sub menu Device specs |
|---|---|--|

[2.1.] Device type MAT 4190 or 4110/220 or 4220 or 4240

In the device type menu the hardware type and the software-release are displayed. Example:


| | |
|---------------------|---|
| MAT 4190 | with 1 measuring circuit (activation code 1.7.1. inactive) |
| MAT 4190/260 | with 2 measuring circuits, but only one is activated (activation code 1.7.1.) |
| MAT 4260 | with 2 active measuring circuits |
| MAT 4240 | with 2 active measuring circuits, plus analog outputs galvanically separated against each other |

Software versions are marked according to NAMUR EN53. (V 1.00)

| | |
|---|--|
|  | After pressing the ok button the display changes to the next menu item 2.2. |
|---|--|

[2.2.] Serial number and date of the system verification

The serial number is fix stored in the **mipromex®** and can not be changed. The serial number is linked to the activation codes. The date of the system verification marks the QS-function control during the final function test.


| | |
|---|--|
|  | After pressing the ok button the display changes to the next menu item 2.3. |
|---|--|

[2.3.] Number of measuring circuits (1. measuring circuit, skip 3.1/4.1)

Here is displayed if there is one or two measuring circuits activated.

Battery type

The inserted battery type is displayed. The battery has not to be charged before using the **mipromex®**. The battery lifetime of 10 years guarantees that no data loss will occur.




After pressing the **ok** button the display changes to the next menu item 2.4.

[2.4.] Select measuring circuit 1 or 2

Select the active measuring circuit for the next steps.

selected menu item is inverted



After pressing the **ok** button the display changes to the menu of the selected measuring circuit (1). 2.4.1.

[2.4.1.] Probe Type 1 / 2

This is an input field. If the system is delivered with a probe, the probe type is stored here.

selected character is inversed 16-char. max



1. use ▲▼◀▶-buttons to input the alpha-numerical type code of the probe
2. press **ok** button more than 2 seconds

Type code is stored
Display changes to the next menu item 2.4.2.

[2.4.2.] Serial No. 1 / 2

This is an input field. If the system is delivered with a probe, the serial no. of the probe is stored here.

selected character is inversed 16-char. max



1. use ▲▼◀▶-buttons to input the alpha-numerical serial number of the probe
2. press **ok** button more than 2 seconds


Serial number is stored
Display changes back to menu 2.4.

4.1.3. [3.] Signal settings

In the signal settings menu all signal related parameters can be set.

Main menu

selected menu item is inverted




After pressing the **ok** button the display changes to the sub menu signal settings

[3.1.] Select measuring circuit 1 or 2

Select the active measuring circuit for the next steps.

selected menu item is inverted



After pressing the **ok** button the display changes to the menu of the selected measuring circuit (1). 3.1.1.

[3.1.1.] Input Pos. No.

You have the possibility to store a Tag No. for the probe in the **mipromex®**. The field is alphanumeric. You can define your position- or Tag-number, 11-characters max. selected character is inverted

| | |
|------------------------|--------------|
| Input Tag.-No.: | |
| 1 Tag. | ----- |
| ▲▼◀▶ adjust | |
| 3.1.1. | Store |

1. use ▲▼◀▶-buttons to input the alpha-numerical position number
 2. press **ok** button more than 2 seconds
- Pos.-No. is stored
Display changes to menu item 3.1.2.

[3.1.2.] Probe factor

The probe factor is a probe specific number which indicates the correlation to the standard probe (factor 1.00). If you replace the probe you will get a reproducible measurement with the same measured values. The probe factor has only to be changed when using a replacement probe. By changing the factor, you will get with the replacement probe, the same pulses value at 100 %

e. g. MeV old probe 2600 / 2955 MeV new probe = f 0.879

The probe factor has only to be changed when using a replacement probe selected character is inverted

| | |
|---------------------|--------------|
| Probe factor | |
| | 1.000 |
| ▲▼◀▶ Adjust | |
| 3.1.2. | Store |

1. use ▲▼◀▶-buttons to define the probe factor
 2. press **ok** button more than 2 seconds
- Probe factor is stored
Display changes to the next menu item 3.1.3. After changing the probe factor the zero point must be actualized and stored 3.1.3.

[3.1.3.] Zero point acceptance at push button (Offset) OK store

The probe electronic is calibrated in the factory to 60 ±2 pulses. If the probe is installed, this value can be higher due to the environment. If the probe is installed; empty and dry, the zero point can be checked and/or manually corrected. Attention: switch-on the unit 30 minutes before the zero adjust. A measured value between 10 and 2000 pulses can be adjusted without performing an electronic calibration. **Attention; Probe must be dry and clean!** MeV = normed measured value in pulses

actual stored zero point offset
actual raw measured value, empty probe

| | |
|------------------------|--------------|
| Zero point MeV | |
| Accept at | |
| pushing button: | 0060 |
| actual MeV: | 0076 |
| 3.1.3. | Store |

1. press **ok** button more than 2 seconds
- The new zero point is immediately activated
Display changes to the next menu item 3.1.4.

[3.1.4.] Manual zero point input (offset)

The programmable probe zero point can be changed or corrected manually. If the installation cannot be emptied for the zero point of the probe, then the zero point is manually keyed-in from the protocol

You can manually correct the zero point of the probe
actual raw measured value of the probe
adjust zero point

| | |
|-----------------------|--------------|
| Zero point MeV | |
| Manual input | |
| Adjust | 0076 |
| ▲▼◀▶ | 0087 |
| 3.1.4. | Store |

1. use ▲▼◀▶-buttons to define the zero point
 2. press **ok** button more than 2 seconds
- The new zero point is immediately activated
Display changes to the next menu item 3.1.5.

[3.1.5.] Measuring span acceptance at push button

The measuring span for the calculation of the 100 % point is product depending. This pulses value is obtained by fully immersing the measuring electrode into the product and by saving "at push button" the measured value. **Attention: this procedure is in dependence of point 3.1.6.**

MS = normed measuring span in pulses
actual stored measuring span
(raw measured value – zero point offset)

| | |
|-------------------------|--------------|
| Meas. span = MeS | |
| Accept at | |
| push button | 2340 |
| actual MeV: | 2255 |
| 3.1.5. | Store |

1. press **ok** button more than 2 seconds
- The new measuring span is immediately activated
Display changes to the next menu item 3.1.7.

[3.1.7.] Measuring span

The measuring span (point 3.1.5) can be changed or corrected here manually.

You can manually correct the Measuring span of the probe
actual measured value of the probe
Adjust measuring span


| | |
|-------------------------|--------------|
| Meas. span = MeS | |
| Manual Input | |
| Adjust | 2255 |
| ▲▼◀▶ | 0255 |
| 3.1.7. | Store |

1. use ▲▼◀▶-buttons to define the measuring span
 2. press **ok** button more than 2 seconds
- The new measuring span is immediately activated
Display changes to the next menu item 3.1.8.

[3.1.8.] Signal filter

With the free selectable filter time constant (max 30 seconds) you can attenuate the raw measuring signal. A way to center the displayed and power output values

Input the filter constant
filter of the first order
actual stored filter constant




1. use ▲▼◀▶-buttons to define the signal filter time
2. press **ok** button more than 2 seconds

The new time is immediately activated
Display changes back to menu 3.1.

4.1.4. [5.] Measuring range


In the measuring range menu all measuring range related parameters can be set.



After pressing the **ok** button the display changes to the sub menu measuring range 5.1.

[5.1.] Select measuring circuit 1 or 2


Select the active measuring circuit for the next steps.



After pressing the **ok** button the display changes to the selected measuring circuit menu (1). 5.1.2

[5.1.2.] Measuring range starting point

Set the start point of the selected measuring range (e.g. **20.0** – 60.0 %). By defining the start and the end point you can **spread** the mA signal and therefore get a higher resolution in this area.




1. use ▲▼◀▶-buttons to define the start point
2. press **ok** button more than 2 seconds

The new spreading is immediately activated

Display changes to the next menu item 5.1.3.

[5.1.3.] Measuring range end point

Set the end point of the selected measuring range (e.g. 20.0 – **60.0** %)




1. use ▲▼◀▶-buttons to define the end point
2. press **ok** button more than 2 seconds

The new spreading is immediately activated

Display changes back to menu 5.1.

4.1.5. [6.] Limit value


In the limit value menu all limit values related parameters can be set.



After pressing the **ok** button the display changes to the sub menu measuring ranges 6.1. select measuring circuit.

[6.1.] Select measuring circuit 1 or 2

Select the active measuring circuit for the next steps.



After pressing the **ok** button the display changes to the selected measuring circuit menu (1). 6.1.2

[6.1.1.] Select static or dynamic

With the static limit value you can:

- obtain a precise and reproducible limit value for a given measuring range corresponding to 100 %
- read a chosen limit value as a percentage and programme it as a limit value
- enter very small limit values, starting at 1.1 %, thanks to the high performance measuring circuit and the precise and reproducible processing of the measurement values

With the dynamic limit value you can:

- detect the limit value inside the length of the active measuring electrode independently of the product's properties and its adherence to the measuring electrode
- only one dynamic limit value should be set for each measuring circuit.
- see diagram for the processing of the measurement value

Diagramm (look on Capitell 2.6)

selected character is inverted

select function

stat/dyn

6.1.1. Store ◀▶

1. Use ▲▼◀▶-buttons to define the function

2. Press **ok** button more than 2 seconds

After pressing the **ok** button, the display changes to the menu

Enter limit value or max limit value and hysteresis

[6.1.2.] Limit value

With the static limit value you:

- get an exact and reproducible limit value for a defined measuring span corresponding to 100 %
- can display read a desired percentage at the desired limit value and program it/store it, as limit value
- can enter exact limit values starting at 1.1% thanks to the precise and reproducible measuring values.

selected character is inverted

Limit value

050.0 %

▲▼◀▶ Adjust

6.1.2. Store

1. use ▲▼◀▶-buttons to define the limit value

2. press **ok** button more than 2 seconds

The selected limit value is immediately activated

Display changes to the next menu item 6.1.4.

Or wen your select dyn...

[6.1.2.] max. Limit value

After entering Dynamic

selected character is inverted

max Limit value

080.0 %

▲▼◀▶ adjust

6.1.2. Store

1. Use ▲▼◀▶-buttons to define the limit value

2. press **ok** button more than 2 seconds

The selected limit value is immediately activated

Display changes to the next menu item 6.1.4.

[6.1.3.] Hysteresis

After entering Dynamic

selected character is inverted

Hysteresis

002.0 %

▲▼◀▶ Adjust

6.1.3. Store

1. Use ▲▼◀▶-buttons to define the hysteresis

2. Press **ok** button more than 2 seconds

After pressing the **ok**-button display changes to the next menu item 6.1.4.

[6.1.4.] Time, drop down delay, 1

The relay- or opto-electronic coupler- transistor- output can be activated with a drop down time delay. Input of the time delay drop, in 1 second steps from 0 - 30 minutes.

selected character is inverted

Time delay, off

00.00 mm.ss

▲▼◀▶ Adjust

6.1.4. Store

1. use ▲▼◀▶-buttons to define the time delay off, drop

2. press **ok** button more than 2 seconds

The selected time delay is immediately activated

Display changes to the next menu item 6.1.5.

[6.1.5.] Time, on delay, 1

The relay- or opto-electronic coupler- transistor- output can be activated with an on/raise time delay. Input of the time delay, of raise, in 1 second-steps from 0 - 30 minutes.

selected character is inverted

Time delay, on
00.00 mm.ss

▲▼◀▶ Adjust

6.1.5. Store ▲▼

1. use ▲▼◀▶-buttons to define the time delay on, raise
2. press **ok** button more than 2 seconds

The selected time delay is immediately activated
Display changes to the next menu item 6.1.6.

[6.1.6.] FSL/FSH Position

Define the security settings of the Relay- or opto-electronic-coupler- transistor- outputs, ...

| Active position | | Measured value | Display | opto-electronic coupler |
|-----------------|-----|-----------------------------------|-------------|-------------------------|
| Fail Safe Low | FSL | is lower than limit value | Lo | de-energized |
| Lo-Alarm | | is higher than limit value | none | switched on |
| Fail Safe High | FSH | is lower than limit value | none | switched on |
| Hi-Alarm | | is higher than limit value | Hi | de-energized |

Chart 5 Fail Safe settings

selected menu item is inverted

FSL/FSH –Position
FSL/FSH

6.1.6. Store ◀▶

1. use ◀▶-buttons to define the opto-electronic coupler-output
2. press **ok** button more than 2 seconds

The selected definition is immediately activated
Display changes back to menu item 6.

[6.1.7.] min/max Measurement value

min meas. value
0125 Imp
max meas. Value
2426 Imp

6.1.7. Next

After pressing the **ok** button the display changes to the sub menu test functions 6.1. select measuring circuit

4.1.6. [7.] Test functions

To test the functions at commissioning, a programmable mA output is available.

Main menu

selected menu item is inverted

Signal settings
Measuring range
Limit value
Test functions

7. Select ▲▼

After pressing the **ok** button the display changes to the sub menu test functions 7.1. select measuring circuit

[7.1.] Select measuring circuit 1 or 2

Select the active measuring circuit for the next steps.

selected menu item is inverted

Select meas. circuit
1/2

7.1. Select ◀▶

After pressing the **ok** button the display changes to the selected measuring circuit menu (1). 7.1.1

[7.1.1.] Simulation of mA- output (in 0.1 mA steps, starting at 0.5 mA)

With this function the active current output (burden 750 Ω) can be tested.

The current output can be increased in 0.1 steps starting at 0.5 mA and ending at max. 22.0 mA.

selected character is inverted

mA-Output
Simulation 00.5 mA

▲▼◀▶ Adjust


7.1.1. Store

1. use ▲▼◀▶-buttons to define the current output
2. press **ok** button more than 2 seconds

Current output is immediately activated
Display changes back to 7.1.

4.1.7. [8.] Programmable mA output


All **mipromex®** microprocessor units are equipped with a diagnostic system, which makes fault-finding easier and facilitates quicker correction in case of malfunction occurrence. The error levels can be set in 0.1 mA-steps between 0.5 - 4.0 and 20.0 - 22.0 mA. Error messages are set at factory to automatically acknowledge the fault. The fault-type is displayed with time and date. By pressing > 2 seconds the **ok** button, the display changes back to the measured value. The error is displayed without measured value ---.- and an arrow up ↑ or down ↓ .



After pressing the **ok** button the display changes to the sub menu fault messages 8.1.

[8.1.] Data error measuring value underflow MeV <0010

The data transmission of the measured value, between measuring electronic MTI and the control unit **mipromex®** is faulty. The control unit **mipromex®** is unable to process the measured data. Error level 1 see fault finding on page 32




1. use ▲▼◀▶-buttons to define the current output
2. press **ok** button more than 2 seconds

Current output is immediately activated
Display changes to the next menu item 8.2.

[8.2.] Data error measuring value overflow MeV >3750

The measured value of the measuring electronic MTI is higher than the allowed range of pulses. The control unit **mipromex®** is unable to process the measured data. Error level 2 see fault finding on page 32




1. use ▲▼◀▶-buttons to define the current output
2. press **ok** button more than 2 seconds

Current output is immediately activated
Display changes to the next menu item 8.3.

[8.3.] Technical Error


The control unit **mipromex®** generates a periodic checksum test. If it is faulty, an error message is displayed. Error level 3 see fault finding on page 32



1. use ▲▼◀▶-buttons to define the current output
2. press **ok** button more than 2 seconds

Current output is immediately activated
Display changes back to menu 8.

4.1.1. [12.] Calculation parameters



After pressing the **ok** button the display changes to the sub menu 12.1. select measuring circuit

[12.1.] Select measuring circuit 1 or 2 (MLS 1200/1270)

With the drift compensation small measurement modifications like temperature drift are compensated for by HF wire or probes. $\pm 1-3$ impulses per minute correspond to normal drift compensation. With the drift compensation the measurement has left constantly if the drift is smaller than the drift gradient. This means the measurement corrects itself the max. drift in impulses is fixed in the drift memory within a minute (adjusting drift time 60 s). The sum of the individual drift compensations becomes e.g. 30 (impulses) to change the measurement more greatly than 30 impulses begin itself into function of the drift. At a zero comparison [3.1.3.] the drift loft is put on 0000. Around min. 40 impulses, the zero comparison must always be GREATER than Max Driftspeicher. The measurement otherwise sinks at a negative drift under the zero. Consequence is: Technical disturbance measurement underrun!

At the measuring of at times slow modifications like filling level measuring the drift compensation must get prepared for 0 Imp, i.e. turned off.

Caution: With the drift compensation no probe pollutions can be compensated for.

Select the measuring circle for the further action.

selected menu item is inverted

| | |
|-----------------------------|------------------|
| Select meas. circuit | |
| 1/2 | |
| 12.1. | Select ◀▶ |

After pressing the **ok** button, display changes to the menu for the measuring circuit selected (1). 12.1.1.

[12.1.1.] Drift memory

selected menu item is inverted

| | |
|-----------------------|--------------|
| drift | |
| actual 212 Imp | |
| max. 500 Imp | |
| ▲▼◀▶ Adjust | |
| 12.1.1. | Store |

1. use ▲▼◀▶-buttons to define max. drift
2. press **ok** button more than 2 seconds
+- drift

If the max. drift is exceeded, no more drift compensation is possible

[12.1.2.] Driftgradient pulses

selected menu item is inverted

| | |
|---------------------|--------------|
| drift pulses | |
| 000 Imp | |
| ▲▼◀▶ Adjust | |
| 12.1.2. | Store |

1. use ▲▼◀▶-buttons to define max. drift pluses
2. press **ok** button more than 2 seconds
+- drift

If the max. drift is exceeded, no more drift compensation is possible

[12.1.3.] Driftgradient time

selected menu item is inverted

| | |
|--------------------|--------------|
| drift time | |
| 0100 s | |
| ▲▼◀▶ Adjust | |
| 12.1.3. | Store |

1. use ▲▼◀▶-buttons to define max. drift time
2. press **ok** button more than 2 seconds
+- drift time

If the max. drift is exceeded, no more drift compensation is possible

5. Commissioning example

Make sure the connections in the Monorack or 19"-Rack are wired correctly and the probe is connected.
The control unit **mipromex®** is installed in the Rack and under tension.
The green or red LED inside the MTI (measuring electronic) of the probe is lit.
The vessel is empty; the probe is dry and clean.
Follow the steps of the commissioning:

5.1. Commissioning the mipromex® with a pipe probe

5.1.1. Detection of water in petrochemical products

The pipe probe is installed in the pipeline. The pipeline must be empty!

| Menu-Code | Description | Example | | Input |
|---------------|---|---|-------------------------------------|-------|
| 2.4.1 | Check the probe type | TSS90 DN50 | | |
| 2.4.2 | Check the serial no. of the probe | 1050066-06 | | |
| 3.1.1. | Enter your TAG-, position- or measuring site- number | LS1200 | | |
| 3.1.2. | Check the probe factor Only to be changed when using a replacement probe | 1.000 | | |
| 3.1.3. | Accept the actual zero point Important: the pipeline must be empty, Important: the pipe probe must be dry and clean Pipe probes are calibrated in the factory to 60 pulses If the probe is already product, please keep the factory settings | ideal between 60 – 80 | | |
| 3.1.5. | Accept measuring span MS: Fill the pipeline with your petrochemical product with the highest water content The MS is product and nominal diameter depending | 5 % water in paraffin oil MS 860 Imp = 100 % | paraffin oil 110 Imp = 12.5 % | |
| 5.1.2. | Define the start point of the signal spread at 4 mA | instead of 0.0 % | new at 10.0 % | |
| 5.1.3. | Define the end point of the signal spread at 20 mA | instead 100.0 % | new at 80.0 % = 4 % water | |

Chart 6 Commissioning of water detection

5.1.2. Oil detection in process- or rain-water

The pipe probe is installed in the pipeline. The pipeline must be empty!

| Menu-Code | Description | Example | | Input |
|---------------|--|-----------------------|---------------------------------|-------|
| 2.4.1 | Check the probe type | TSS90 DN50 | | |
| 2.4.2 | Check the serial no. of the probe | 1050066-06 | | |
| 3.1.1. | Enter your TAG-, position- or measuring site- number | LS1200 | | |
| 3.1.2. | Check the probe factor Only to be changed when using a replacement probe | 1.000 | | |
| 3.1.3. | Accept the actual zero point Important: the pipeline must be empty Important: the pipe probe must be and clean Pipe probes are calibrated in the factory to 60 pulses If the probe is already soiled with product, please keep the factory settings | ideal between 60 – 80 | | |
| 3.1.5. | Accept measuring span MS: Fill the pipe with your process water The MS depends on the product and the nominal diameter | water MS 2570 Imp | 5 % oil in water 2050 Imp | |
| 5.1.2. | Define the start point of the signal spread at 4 mA | instead of 0.0 % | new at 80.0 % | |
| 5.1.3. | Define the end point of the signal spread at 20 mA | instead 100.0 % | remains at 100.0 % | |

Chart 7 Commissioning of oil detection

5.2. Commissioning the mipromex® with a bar probe

5.2.1. Oil detection in process- or rain-water with float

Bar probe is installed and adjusted in the float. The bar probe must be dry and clean!

| Menu-Code | Description | Example | | Input |
|-----------|--|---|--|-------|
| 2.4.1 | Check the probe type | STM 180/100 SB R TN ES SW V | | |
| 2.4.2 | Check the serial no. of the probe | 1050066-06 | | |
| 3.1.1. | Enter your TAG-, position- or measuring site- number | LS1200 | | |
| 3.1.2. | Check the probe factor Only to be changed when using a replacement probe | 1.000 | | |
| 3.1.3. | Accept the actual zero point Important: the bar probe must be dry and clean If the probe is already soiled with product please keep the factory settings | ideal between 60 – 80 | | |
| 3.1.5. | Accept measuring span MS: Bar probe is 100 % immersed in your process water Accept the measured value as measuring span Probe 100 mm in water = 100% Probe 80 mm in water and 20 mm in oil | 100 mm water 2700 Imp = MS =100% | 80 mm water 20 mm oil 2200 Imp = 81 % | |
| 5.1.2. | Define the start point of the signal spread at 4 mA | instead of 0.0 % | new at 80.0 % | |
| 5.1.3. | Define the end point of the signal spread at 20 mA | 100.0 % | remains at 100.0 % | |

Without an oil layer at surface of water, the display shows 100% = 20.0 mA
Chart 8 Commissioning of oil layer detection

5.2.2. Foam detection



Attention:

A limit switch detection of the top of the foam is a relative measurement.
Due to varying structure and consistence, and foam plus product variations, the measurement can not be considered as a filling level measure.

Bar probe is installed in the vessel. The bar probe must be dry and clean!



| Code | Description | Example | | Input |
|---|---|-------------------------------|--------------------|-------|
| 2.4.1 | Check the probe type | ST2M 500/300 SB T2R GS DN50 C | | |
| 2.4.2 | Check the serial no. of the probe | 1050066-06 | | |
| 3.1.1. | Enter your tag-, position- or measuring site-number | LS1200 | | |
| 3.1.2. | Check the probe factor Only to be changed when using a replacement probe | 1.000 | | |
| 3.1.3. | Accept the actual zero point Important: the bar probe must be dry and clean If the probe is already soiled with product, please keep the factory settings | ideal between 60 – 80 | | |
|  | If the measured value shows > 400 an electronic calibration is recommended Point 5.3 page 29 Otherwise the measuring span MS is limited | | | |
| 3.1.5. | Accept measuring span MS: Immerse the probe 100 % in your foam and accept the measuring span If the probe is not fully immersed, the measuring span must be calculated to 100 % and keyed-in at menu item 3.1.7. | Full range 1270 Imp | 50 % 635 Imp | |
| 5.1.2. | Define the start point of the signal spread at 4 mA | 0.0 % | remains at 0.0 % | |
| 5.1.3. | Define the end point of the signal spread at 20 mA | 100.0 % | remains at 100.0 % | |
| 6.1.2. | max. Limit value | 80 % | | |
| 6.1.3. | Limit switch detection by hysteresis | 10 % | | |
| 6.1.4. | Time, drop down delay, 1 | 00.02 | | |

Chart 9 Commissioning of foam detection

5.3. Electronic calibration MTI, basic equalization

An electronic calibration has only to be done at following occurrences:

- ☑ Probes without reference electrode, flexible- or flat-probes where the *measured value* inside the *empty* vessel is smaller than 10 or bigger than 200
- ☑ After exchange of the measuring electronic MTI, or of the coax cable, or of the probe, or after repair of the probe
- ☑ If the zero adjust is not possible: displayed measured value >2000 or <10

**Tip:**

Adjust the measuring electronic MTI between 60 and 80 pulses
This allows the biggest possible measuring span of up to max. 3750 pulses.
Soiled or uncleaned probes should not be adjusted with an MTI calibration.




| | | |
|---|---|---|
|  | <i>Probe dry and clean, built in the vessel</i> | Go to the menu point 3.1.3. |
|  or  | <i>Calibration of MTI as follows:</i> Using a screwdriver size No. 1, fine adjust to switch point of the LED from red to green (red will flicker). Display between 60 and 80 | |
| <p>The 0-point has been stored at the system test. If the probe is built in, dry and empty the 0-point can be checked and corrected.</p> <p>Menu position Number-Code</p> | <div><div>Zero point MeV</div><div>Accept at</div><div>push button 0060</div><div>actual MeV 0085</div><div>3.1.3. Store</div><div>change to the next menu item by pressing the Ok button</div></div> | <p>1. press ok button more than 2 seconds:</p> <p>actual MeV is stored Display changes to the next parameter input</p> |

Chart 10 Electronic calibration operating sequences

5.4. Inspection release of the parameters

Operating parameters (settings at final inspection on site at commissioning)

| | |
|----------------|-------------------|
| Company _____ | Order _____ |
| Building _____ | PO no. _____ |
| Plant _____ | Project no. _____ |

| | | | | | | |
|-----------|------------|-------|--------------------------------|------------------------------|---------------------------------|------------------|
| mipromex® | MLS | V1.12 | Ex ia <input type="checkbox"/> | Exd <input type="checkbox"/> | Non-ex <input type="checkbox"/> | Serial no. _____ |
|-----------|------------|-------|--------------------------------|------------------------------|---------------------------------|------------------|

| | |
|---|--------------------|
| Measuring circuit 1 | Pos./Tag no. _____ |
| Probe type _____ | Serial no. _____ |
| Coax cable _____ Serial no. _____ MTI _____ | Serial no. _____ |

| | |
|---|--------------------|
| Measuring circuit 2 | Pos./Tag no. _____ |
| Probe type _____ | Serial no. _____ |
| Coax cable _____ Serial no. _____ MTI _____ | Serial no. _____ |

Chart for operating settings

| Menu item | Meas. circuit | Description | Final inspection | Commissioning |
|----------------------------|---------------|---|-----------------------------|------------------------------|
| 1. Basic settings | | | | |
| 1.1. | | Language Deutsch/Français/English | English | |
| 1.2.1. | | Time | Local time | Local time |
| 1.2.2. | | Date | Local date | Local date |
| 1.3.1. | | Password | 0000 | |
| 1.4.1. | | Lighting | on | |
| 1.4.2. | | Lighting time in minutes | 1 | |
| 1.6.1. | | Store the parameters | OK <input type="checkbox"/> | OK <input type="checkbox"/> |
| 1.6.2. | | Load the parameters | press OK button >2s | |
| 1.6.3. | | Initialize the device | | Yes <input type="checkbox"/> |
| 1.7.1. | | Activation for the 2nd measuring circuit | | |
| 2. Device data | | | | |
| 2.1. | | Device type Software version | MLS V1.12 | MLS V |
| 2.2. | | Serial no. Testing date | | |
| 2.3. | | Number of measuring circuits / Battery type: CR2032 | | |
| 2.4.1. | MC1 | Probe type | | |
| 2.4.2. | MC1 | Probe serial no. | | |
| 2.4.1. | MC2 | Probe type | | |
| 2.4.2. | MC2 | Probe serial no. | | |
| 3. Signal settings | | | | |
| 3.1.1. | MC1 | Entry of position/TAG no. | | |
| 3.1.2. | MC1 | Probe factor | 1.000 | |
| | | Zero adjustment for tube/bar probe empty/clean | | |
| 3.1.3./4. | MC1 | Zero point importing on keystroke / manual entry Imp | | |
| 3.1.5./7. | MC1 | Measuring span importing on keystroke / manual entry / adjustment Imp | | |
| 3.1.8. | MC1 | Signal filter s | 00.1 | |
| 3.1.1. | MC2 | Entry of position/TAG no. | | |
| 3.1.2. | MC2 | Probe factor | 1.000 | |
| | | Zero adjustment for tube/bar probe empty/clean | | |
| 3.1.3./4. | MC2 | Zero point importing on keystroke / manual entry Imp | | |
| 3.1.5./7. | MC2 | Measuring span importing on keystroke / manual entry / adjustment Imp | | |
| 3.1.8. | MC2 | Signal filter s | 00.1 | |
| 5. Measuring ranges | | | | |
| 5.1.1. | MC/DO1 | Measuring range unit | | |

| | | | | |
|---------|-------------------------------|---|-------------------------------|-------------------------------|
| 5.1.1. | MC/DO2 | Measuring range unit | | |
| 6. | Limit values | | | |
| 6.1.2. | MC1/DO1 | Selection: stat / dyn | | |
| 6.1.3. | MC1/DO1 | Set limit value 1 / (max. limit value → dyn) | % | |
| 6.1.4. | MC1/DO1 | Hysteresis (→ dyn) | Imp | |
| 6.1.5. | MC1/DO1 | Time delay, off | mm.ss | 00.00 |
| 6.1.6. | MC1/DO1 | Time delay, on | mm.ss | 00.00 |
| 6.1.7. | MC1/DO1 | FSL / FSH position | | FSL |
| 6.1.8. | MC1/DO1 | min/max limit value display (→ dyn) | | |
| 6.1.1. | MC1/DO2 | Selection: Limit value / Fault message → MLS 1100 / 1101 / 1170 only | | |
| 6.1.2. | MC2/DO2 | Selection stat / dyn | | |
| 6.1.3. | MC2/DO2 | Set limit value 1 / (max. limit value → dyn) | % | |
| 6.1.4. | MC2/DO2 | Hysteresis (→ dyn) | Imp | |
| 6.1.5. | MC2/DO2 | Time delay, off | mm.ss | 00.00 |
| 6.1.6. | MC2/DO2 | Time delay, on | mm.ss | 00.00 |
| 6.1.7. | MC2/DO2 | FSL / FSH position | | FSH |
| 6.1.8. | MC2/DO2 | min/max limit value display (→ dyn) | | |
| 7. | Test functions | | | |
| 7.1.3. | MC1/DO1 | Limit value 1 simulation OFF/ON | <input type="checkbox"/> i.O. | <input type="checkbox"/> i.O. |
| 7.1.4. | MC2/DO2 | Limit value 2 simulation OFF/ON | <input type="checkbox"/> i.O. | <input type="checkbox"/> i.O. |
| 8. | Fault messages | | | |
| 8.1. | | Actual fault with time/date | | |
| 12. | Calculation parameters | | | |
| 12.1.1. | MC1 | Maximal drift storage in pulses | Imp | 0100 |
| 12.1.2. | MC1 | Drift pulses per time unit | Imp | 0 |
| 12.1.3. | MC1 | Drift time | s | 0060 |
| 12.1.1. | MC2 | Maximal drift storage in pulses | Imp | 0100 |
| 12.1.2. | MC2 | Drift pulses per time unit | Imp | 0 |
| 12.1.3. | MC2 | Drift time | s | 0060 |
| 1.6.1. | | Storing the parameters | OK <input type="checkbox"/> | OK <input type="checkbox"/> |

Final inspection carried out by:

Commissioning carried out by:

Aquasant Messtechnik AG / Bubendorf /

6. Fault finding

All **mipromex** –microprocessor units are equipped with a diagnostic system, which makes fault finding easier and facilitates quicker correction in case of malfunction occurrence.

6.1. After power on

7.1.1. Technical error; All oder Nv Init from Flash oder low Battery

The error message can have different origin.

1. RAM memory check has failed

| | |
|-------------------|--------------------|
| Date of error | 02.11.08 |
| Time of error | 16:11:10 |
| Error description | Nv Init from Flash |

1. press **ok** button more than 2 seconds, the error is confirmed and the display changes back to last active menu point

2. Flash memory check has failed

| | |
|-------------------|---------------------|
| Date of error | 02.11.08 |
| Time of error | 16:11:10 |
| Error description | All Init from Flash |

1. press **ok** button more than 2 seconds, the error is confirmed and the display changes back to last active menu point

3. Battery is discharged and has to be exchanged

| | |
|-------------------|-------------|
| Date of error | 02.11.08 |
| Time of error | 16:11:10 |
| Error description | Low Battery |

1. press **ok** button more than 2 seconds, the error is confirmed and the display changes back to last active menu point

Switch OFF and then switch ON the unit. If error reoccurs then:

Send unit back for repair! 

6.2. During operation

6.2.1. Data error

7.1.1. Technical error; Measured value 1 underflow

The error message can have different origin.

| | |
|--------------------------|-------------------------|
| Date of error | 02.11.07 |
| Time of error | 16:11:10 |
| Measuring circuit 1 or 2 | Data error |
| Error description | Meas. value 1 Underflow |

1. press **ok** button more than 2 seconds, the error is confirmed and the display changes back to last active menu point

The mA output falls to the value programmed under menu point 8.3!

| | |
|---|-----------------------------------|
| Description of 1 st meas. circuit position | 1 Pos. QLA12345679 |
| Description of 1 st meas. value | Analog output 1 |
| Non display of meas. value | ---.- % Lo ↓ |
| Error display | Menu ▼▲▼ |
| ok button-functions / active keys | Press Ok to change to menu |

Limit value low alarm is reached
Arrow down ↓ **signalizes : Meas. range underflow**

use the ▲▼ buttons to scroll within display mode

| | |
|--|----------------|
| Description of the outputs | Analog outputs |
| Description of 1. and 2. meas. value | 1 00.50 mA |
| Display of actual value of current outputs | 2 11.20 mA |
| ok button-functions / active keys | Menu ▲▼ |

Press **Ok** to change to menu

use the ▲▼ buttons to scroll within display mode



LEDs on measuring electronic MTI are dark/OFF

1. Short circuit or circuit break. Change connection wires on clamp 1 / 2 of probe electronic.

Check connections of measuring electronic MTI

2. Hazardous area output microprocessor unit **mipromex®** or measuring electronic MTI defective

Send unit back for repair! .

The electronic insert MTI is plugged in the blue protection housing. Loosen the two outer M4-screws and remove the electronic insert MTI laterally towards the cable gland.



LED's on measuring electronic MTI are ON

3. Range monitoring did respond, measured value <10

Check with 0-point-function at menu item 5.3. , perform a new zero adjust

4. Coax cable or probe defective (circuit break)

Send coax cable and probe back for repair! .



Calibration of MTI was possible, microprocessor unit mipromex® showing fault or after power cut showing measured value underflow (no measure):

5. Hazardous area data input of **mipromex®** defective;

Send mipromex® unit back for repair! .


7.1.1.

Technical error; Measured value 1 overflow

The error message can have different origin.

Date of error
Time of error

Measuring circuit 1 or 2
Error description




1. press **ok** button more than 2 seconds, the error is confirmed and the display changes back to last active menu point

Description of 1st meas. circuit position
Description of 1st meas. value



Non display of meas. value
Error display

ok button-functions / active keys




Press **Ok** to change to menu

Limit value high alarm is reached
Arrow up ↑ signalizes : Meas. range overflow



use the   buttons to scroll within display mode

Description of the outputs
Description of 1. and 2, meas. value
Display of actual value of current outputs

ok button-functions / active keys



Press **Ok** to change to menu

use the   buttons to scroll within display mode

Check probe, product intrusion



LEDs on MTI measuring electronic are ON

6. Range control active, measured value >3750

∫ **Scheck with 0-point function under Menu 5.3, perform new basic calibration**

∫ Probe not covered (empty), coax cable or probe defective (coax plug wet)

∫ Fault occurs only when probe covered (full): Impedance in function of product too high:



Send probe back for repair!

6.2.2. Display error



Faulty or no display on the LCD display

1. Restart the program after 5 seconds of mains interruption.

6.2.3. Radio equipment




Radio/wireless equipment should not be operated in the immediate vicinity of the microprocessor unit **mipromex®**, of an open MTI measuring electronic or of the bar probe (measurements can be affected)



Minimum distance 1 to 2 m

7. Wiring diagram

7.1. Measuring electronic/probe with fix connection




Pic. 4 Wiring diagram

1. 2 x 0.75 mm² shielded (both sides earthed in switch room and probe head)
2. MTI housing and probe are connected to the (factory/plant) equipment earths
3. Mains 24 V AC 50/60 Hz /DC ±10 % control voltage, polarity independent, without inductive load
4. Equipotential bond
An equipotential bond must be fitted between the control room earth and the equipment earth (condition of hazardous area protection and for accurate data transmission)

7.2. Connections to female multipoint connector with 32 poles, type: MAT 4190

Microprocessor units with one measuring circuit input
Connections to female multipoint connector FI 32



ELECTRICAL DATA

Euro plug-in card pin assignment

24 V-Version

Error message programmable in
 0.1 mA-steps;
 0.5 – 3.9 / 20.1 – 22 mA

Pic. 5 FI 32 female multipoint connector to MAT 4190

Switch point 1 for measuring circuit 1 **FSL** (Fail Safe Low) **Lo-Alarm**

Switch point 1 for measuring circuit 1 **FSH** (Fail Safe Low) **Hi-Alarm**

Relay 1 disabled (measured value < limit switch value)

Switch point 2 not activated



Technical error level of analog output according to parameterization

Relay 1/2 disabled

ge Clamp® connection clamps for cable diameter 0.08 – 2.5 mm² bared length 5 – 6 mm /0.22 in (without

Color coding:


- Dimension:** H x B x T 137 x 77 x 210 mm / for 19"-plug in module Euro 3 HE/12TE profundity 160 mm

Artikel-Nr.: 02.03.18.011

Seite 40

7.4. Earthing of microprocessor units and probes

Equipotential bond and correct earthing for the hazardous area protection and against disturbances of the data transmission



Pic. 7 Earthing principle

8. Technical Data

8.1. mipromex® Analog transmitter type: MAT 419x

Construction

19"-plug in module, with aluminum-steel housing; IP 20

Assembly

19"-Rack type MR 7; 3 HE (Europ.sizes)
Monorack type MRM2; plastic housing for DIN-rail- or wall mounting.
Front plate fitting with Bopla housing.
Compact or table top housing

Purpose

- analog transmitter with intrinsically safe supply for one measuring electronic MTI xx. Transformation of a digital measuring signal into an analog signal with measuring range spread
- analog output 4 – 20 mA
- menu driven, multi language unit
- hazardous area (Ex) supply for one measuring electronic MTI xx
- shielded 19" plug in module
- one open collector outputs NPN

Operation/Display

Film keypad-front plate with graphical LCD-display, backlit, 6 buttons for data and parameter input

Data saving during power cuts

Battery buffer max. 10 years. Parameter storage into flash at battery failure

Dimensions

Height 3 HE; Width 12 TE
Front plate: Height x width 128 x 61 mm
Plug in module: Height x width x depth 100 x 60 x 160 mm
7 units can be inserted on a 19"-rack

Weight

690 g

Mains supply

24 VAC 50/60 Hz $\pm 10\%$ / 24 VDC Range 18 – 36 VDC
independent of polarity

Switch on current

momentary (1ms) approx. 1A

Power input t

ca. 3.4 VA (I = 140 mA)

Fuses

8.5 x 8.5 mm miniature fuse MST 400 mA

Hazardous area supply and signal transmission

[Ex ia] IIC Pulse modulated supply signal
open circuit voltage max. 18.9 V; typically 17 V
short circuit current max. 49 mA; typically 40 mA

[Ex d ia], Pulse modulated supply signal
open circuit voltage max. $U \leq 19.3$ V; typ. 17 V
short circuit current max. $I \leq 75$ mA; typ. 70 mA

Signal transmission

1 measuring circuit, pulse modulated supply signal

Signal line short circuit

power input max. MAT 4110: 160 mA

Ambient temperature

0 °C ... 45 °C

Storage temperature

–20 °C ... +45 °C, ideally 20 °C

Measurement range

0 – 3700 pulses

Data display

MeV 0 – 3700

Switching hysteresis

1 pulse = 0.028 pF for the 100 pF measuring range

Connection

32 pole FI connector, coding facility

Relaysoutput

1 relay per measuring point with a changeover contact for the limit value. Example: min./max. Deviation min. or max. selectable safety value. Switching voltage 30 Vdc / 2 A, I/O=2kV, –40 to 85°C

Analog output

one active 4 – 20 mA output, max.working resistance/burden 750 Ω , not for hazardous area, with potential separation, tech. fault 0.5 – 4 / 20 – 22 mA adjustable


Interface

RS 232 / RS 485

Monitoring

Self-monitoring detection system for: defective probe; short circuit/interruption signal supply to hazardous area (cable break security); measurement range; main power interruption
mipromex® -error messages

Test and certification

 II (2) G [Ex ia] IIC
II (2) D [Ex iaD]
II (2) GD


RL 94/9/EG SEV 09 ATEX 0132

Confidential test report No.: 08-IK-0396.01 with amendment 1
Unit also available without hazardous area protection

The **mipromex®** must be installed outside of the Ex-Zone
Ex-connection:

Measuring electronic MTI ... in protection housing or bar probe type
S**; K**; F*

EMC-tested, STS 024 report NR. 990102WS corresponds to

| | | |
|-----------------|-------------------|---|
| EN 1127-1:2007 | |  |
| EN 61241-0:2006 | EN 61241-11 :2006 | |
| EN 60079-0:2006 | EN 60079-11 :2007 | |

8.2. Measuring electronic MTI for measuring probes

Probes with separate or integrated measuring electronic MTI

Hotspots

- MTI – measuring electronic in protection housing
- for bare-, strip- and pipe probes with and without measuring electronic in the connection head
- Measuring electronic slot
- Ex-version ATEX ExG / ExD

MTI structure:

- Aluminium gush, Inox or Polyester-protection housing IP 65
- Cover and screw are saved
- Viton cover joint
- screwed cable gland M16 x 1.5 or M20 x 1.5

Dimension:

Aluminium gush-housing: H x B x L = 57 x 80 x 125 mm
 Inox-housing: H x B x L = 85 x 82 x 142 mm
 Polyester-housing: H x B x L = 55 x 80 x 110 mm

Definition:

Under value -10/+0 pF // upper value -0/+10 pF

Temperature range:

-40 bis +60 °C ambient air temperature

Connection:

For all S*K ** bar- and TSS pipe probes with HF-connection

Article-N°.: 02.24.06.0000

| | | | | | | | | | | |
|-------------------------|-----|------|---|----|---|---|---|--|---|---|
| Example: MTI in housing | MTI | 50/2 | A | Gv | L | - | 2 | | K | H |
| Example: MTI slot | MTI | 50/2 | A | E | - | E | 2 | | K | H |

| | | | | | | | | | | |
|---------------|-----|--|--|--|--|--|--|--|--|--|
| Your version: | MTI | | | | | | | | | |
|---------------|-----|--|--|--|--|--|--|--|--|--|

MTI = measuring electronic slot MTI

Measuring range:

| | | | |
|-----|---|----------------|----|
| 10 | = | 3000 Imp/10 pF | |
| 15 | = | 2400 Imp/10 pF | |
| 20 | = | 1600 Imp/10 pF | |
| 50 | = | 650 Imp/10 pF | 50 |
| 100 | = | 350 Imp/10 pF | |
| 200 | = | 180 Imp/10 pF | |
| 300 | = | 120 Imp/10 pF | |
| 400 | = | 90 Imp/10 pF | |
| 600 | = | 60 Imp/10 pF | |
| ... | = | Special range | |

Base calibration range:

| | | | |
|------|---|--------------------------------------|--|
| 0 | = | calibration range in pF of measuring | |
| 1... | = | calibration range in pF of measuring | |

Measuring technology:

| | | | |
|---|---|---|---|
| A | = | Analog measuring technics for interface | A |
|---|---|---|---|

Form or housing version

| | | | |
|----|---|--|----|
| E | = | Slot | E |
| G | = | Protection housing IP 65 blue powder coated angled | |
| Gd | = | Protection housing IP 68 blue powder coated | |
| Gv | = | Protection housing IP 68 stainless steel | Gv |
| Gk | = | Protection housing IP 65 Polyester conductive | |

Connection to the probe:

| | | | |
|---|---|------------------------|--|
| K | = | UHF-connection | |
| L | = | Lemo-connection | |
| S | = | dual HF-connection SMA | |

Slot-version:

| | | | |
|---|---|--|---|
| E | = | measuring electronic slot angled | E |
| R | = | measuring electronic slot round (old) | |
| O | = | measuring electronic slot round for ExD-head | |
| K | = | measuring electronic slot angled for plastics-head | |

Ex-version: SEV 09 ATEX 0133 X / CE 0036/049

| | | | |
|---|---|--|---|
| 0 | = | without protection for hazardous area CE | |
| 2 | = | protection for hazardous area II 2G Ex ia IIC T6 / II 2D | 2 |

Differential measuring:

| | | | |
|---|---|---|--|
| 2 | = | 2. Measuring input for compensation (Antistatic protection) | |
|---|---|---|--|

Trimmer:

| | | | |
|---|---|--|---|
| K | = | 20 pF Ceramic trimmer (vibrationsfest) (all MTI from 10 to 50) | K |
|---|---|--|---|

Version:

| | | | |
|---|---|--|---|
| H | = | increased ESD (electrostatic) protection | H |
|---|---|--|---|



Pic. 8 Measuring electronic

8.2.1. Technical Data MTI . . . / .

Construction/design type

Plug-in measuring electronic with stainless steel cover in protection housing, with coax connection

Installation

Protection housing with mounting holes, plug-in electronic insert, mounting with 2 screws

Function

Linear conversion of an impedance range into a digital measuring norm signal

Operation/display

One time only calibration of the coax cable and the (dry, clean, empty) probe. LED display for quick setting

Housing

Cast aluminum housing, powder coated, solvent resistant, cover and screws secured; IP 65; coax probe connector and cable gland M16, IP 65; blue color coded

Dimensions

Height x width x length 57 x 80 x 175 mm

Weight of electronic

140 g

Weight of housing

740 g incl. MTI and transmitter

Supply/connection hazardous area

Shielded 2 core cable 0.75 mm² to all microprocessor measuring and control units types mipromex®; cable length up to (200m) or max. C = 120 nF / R = 30 Ohm line impedance.

Transmission signal

Pulse packages, superimposed to the power supply

Measuring circuit voltage/current

V ~ 11 V I ~ 13,5 mA

Nominal data of supply voltage

U_N ≤ 18,9 V I_N ≤ 49 mA
C_{imax} 60 nF L_{imax} ≤ 0 mH
P₀ ≤ 231 mW

Ambient temperature

-20 . . . +60 °C

Storage temperature

-30 up to +80 °C, ideally +20 °C

Measurement range

10 / 20 / 50 / 100 / 200 / 300 corresponding to 0 to 3500 pulses, special ranges can be supplied, max. pulse range 3700 pulses

Resolution

Max. 0.003 pF/pulse

Standard measuring range for bar probes

Type STK .../100/200/300
55 pF, Type MTI 50/(0 - 16) basic calibration range (0 - 16) depending on coax cable and probe length, is determined by manufacturer

Basic calibration range

MTI .../. 0 up to 16, 0 to 500 pF

Monitoring frequency

~ 500 kHz

Linearity

Deviation < 0,1 % (without probe)

Hysteresis

1 monitoring pulse

Influence of temperature 5 – 45 °C

Type MTI .../.D digital: < ± 10 measurement pulses
Type MTI .../.A analog: < ± 3 measurement pulses

Test and certification

Ex II 2 G Ex ia IIC
II 2 D Ex iaD
II 2 GD

RL 94/9/EG SEV 09 ATEX 0133 X

confidential test report N° : 08-IK-0396-01

| | | |
|-----------------|-------------------|----|
| EN 1127-1:2007 | EN 60079-26 :2007 | CE |
| EN 61241-0:2004 | EN 61241-11 :2006 | |
| EN 60079-0:2006 | EN 60079-11 :2007 | |

Unit also available without (Ex-Zone) hazardous area protection

Only for connection to microprocessor unit mipromex®

SEV 09 ATEX 0132 Ex II (2)G [Ex ia] IIC
EMC-tested, STS 024 test report N° : 990102WS corresponds to
directive 94/9/EG CENELEC Norms
EN 50081-2: 1993
+ EN 50082-2: 1995
+pr EN 50082-2: 1996

Feed line to probe

Version

- MTI fix mounted onto probe

- Coax cable with UHF plug on both ends

Mounting

Screw in UHF plugs and shrink heat-shrinkable sleeves

Length

0.3 m, 1 m, 2 m and 3 m

Code color brown

High temperature resistant up to 200 °C, Teflon coated, only suitable for permanent installations

Code color blue

Highly flexible, temperature resistant up to max. 80 °C
Deviation at cable move ±2 measuring pulse

Index

1

| | |
|--------------------------|----|
| 1 measuring circuit..... | 14 |
|--------------------------|----|

2

| | |
|---|----|
| 2 measuring circuits | 14 |
| 2 nd measuring circuit, activation | 22 |

A

| | |
|---|--------|
| Activation code | 22 |
| Activation code, Menu- | 16 |
| Activation of 2 nd measuring circuit | 22 |
| Active dataset, protocol, Menu- | 17 |
| Active part..... | 11 |
| Ambient temperature | 42 |
| Ambient temperature MTI..... | 44 |
| Analog output..... | 42 |
| Analog output 1(display)..... | 14 |
| Analog output 2 (display)..... | 14 |
| Analog outputs %(display) | 14 |
| Analog outputs galvanically separated..... | 22 |
| Analog outputs mA (display) | 14 |
| Aquasant Measuring Technique Ltd, Switzerland | ii |
| Aquasant Messtechnik AG, Schweiz..... | ii |
| Aquasant Measure Technique S.A., Suisse..... | ii |
| aquasant-mt = www.aquasant-mt.com | ii, 19 |
| Archive, Menu- | 17 |
| Arrow down ↓ signalizes | |
| Meas. range underflow | 35 |
| Arrow up ↑ signalizes | |
| Meas. range overflow | 36 |
| Assembly..... | 42 |
| ATEX..... | 44 |

B

| | |
|-----------------------------------|----|
| Bar probe | 11 |
| Basic calibration range MTI | 44 |
| Basic equalization..... | 32 |
| Basic settings..... | 19 |
| basic settings, Menu | 16 |
| Battery type..... | 23 |
| Battery type, Menu..... | 16 |
| Burden 750 Ohms- | 27 |

C

| | |
|-------------------------------------|--------------|
| Calculation parameters, Menu- | 17 |
| Cleaning of units | 7 |
| Code color blue..... | 44 |
| Code color brown | 44 |
| Code parameter, Menu- | 16, 17, 18 |
| Code, activation | 22 |
| Code, type..... | 8, 9, 10, 16 |
| Commissioning..... | 30 |

| | |
|---|----|
| Commissioning according to..., Menu | 17 |
| Commissioning, with a bar probe | 31 |
| Commissioning, with a pipe probe TSS90..... | 30 |
| Conductivity | 11 |
| Connection..... | 42 |
| Connection to female multipoint connector | 39 |
| Construction..... | 42 |
| Construction/design type MTI | 44 |
| Contact- | 21 |
| Contact information, Menu- | 16 |
| Controller function, Menu- | 17 |

D

| | |
|--|--------------------|
| Data display | 42 |
| Data error-..... | 35 |
| Data error, measuring value overflow | 28 |
| Data error, measuring value underflow | 28 |
| Data input, structure..... | 13 |
| Data saving during power cuts..... | 42 |
| Detection of oil in process or rain water..... | 30 |
| Detection of water in petrochemical products | 30 |
| Device specs | 22 |
| Device specs, Menu | 16 |
| Device type (display) | 14 |
| Device type MAT..... | 22 |
| Diagnosesystem | 28 |
| Diagnostic system..... | 35 |
| Dielectrical constant..... | 11 |
| Dimensions | 42 |
| Dimensions MTI | 44 |
| Display at switch on..... | 14 |
| Display modes, Menu | 18 |
| Display, Analog output 1 | 14 |
| Display, Analog output 2 | 14 |
| Display, Analog outputs mA | 14 |
| Display, Device type | 14 |
| Display, error | 37 |
| Display, software release..... | 22 |
| Display, type code | 23 |
| Display, Zero point MeV | 32 |
| dry and clean (probe must be...) | 24, 30, 31, 32, 44 |
| Dynamische Messwertverarbeitung | 12 |

E

| | |
|---|--------|
| Earthing of...- | 41 |
| Electronic calibration | 32 |
| Equipotential bond..... | 38, 41 |
| equipotential bond line..... | 41 |
| Error level, programmable- | 28 |
| Error message mA output, Menu | 17 |
| Error, technical-..... | 28 |
| Error, technical- level | 39 |
| Ex- Supply/connection hazardous area MTI..... | 44 |

F

| | |
|------------------------------|----|
| factory settings | 21 |
| Factory settings, Menu | 16 |
| Fail Safe High | 27 |

| | |
|-------------------------------------|--------|
| Fail Safe Low | 27 |
| Fault finding | 28, 35 |
| Fault finding, after power on | 35 |
| Fault finding, data error | 35 |
| Fault finding, operation | 35 |
| Feed line to probe | 44 |
| Foam detection | 31 |
| FSL Fail Safe Low | 39 |
| FSL/FSH position | 27 |
| Function | 11 |
| function MTI | 44 |
| Fuses | 42 |

G

| | |
|-----------------------|----|
| Graphic display | 14 |
|-----------------------|----|

H

| | |
|---|-------|
| Hardware, types | 8, 22 |
| Hazardous Area / Plant | 38 |
| Hazardous Area protection | 6 |
| Hazardous area supply and signal transmission | 42 |
| Hi Alarm High Low | 27 |
| Housing MTI | 44 |
| Hysteresis MTI | 44 |

I

| | |
|--|----|
| Impedance, bar probe | 11 |
| Impedance, function | 11 |
| Impedance, max, supply line Ex Zone | 44 |
| Impedance, measured value | 11 |
| Impedance, normed measuring signal | ii |
| Impedance, pipe probe | 11 |
| Impedance, probe | 6 |
| Impedance, range | 44 |
| Impedance, sum signal | 11 |
| Impedance, too high, fault | 37 |
| Influence of temperature MTI | 44 |
| Information / Notice | 3 |
| Initialize unit | 21 |
| Input / changing of chracters | 13 |
| Input field | 13 |
| Input Pos. No. | 24 |
| Inspection release of the parameters | 33 |
| Installation | 6 |
| Installation MTI | 44 |
| Interface | 42 |

K

| | |
|----------------------------------|----|
| Key -C- =/back/delete/ | 13 |
| Key description | 13 |
| Key -down- | 13 |
| Key functions | 13 |
| Key in Password, (display) | 19 |
| Key -left- | 13 |
| Key -OK- | 13 |
| Key -right- | 13 |
| Key -up- | 13 |
| Keypad | 6 |
| Keypad buttons | 11 |
| Keypad frontplate | 42 |

L

| | |
|--|--------|
| Language, 4 th , to program | 13 |
| Language, Menu | 16 |
| Language/Sprache | 19 |
| Languages Deutsch/English/Français | 13 |
| Lightning | 20 |
| Lightning settings- | 20 |
| Lightning, Menu- | 16 |
| Limit value | 25, 26 |
| Limit values, Menu- | 17 |
| Linearity MTI | 44 |
| Lo Alarm Low | 27 |
| Load parameter set | 21 |

M

| | |
|--|------------|
| mA output, simulation | 27 |
| mA, active current output | 27 |
| mA, programmable error level output | 28 |
| Mains supply | 42 |
| Maintenance | 7 |
| MAT 4110 | 22 |
| MAT 4110/220 | 22 |
| MAT 4190, technical data | 42 |
| MAT 4220 | 22 |
| MAT 4240 | 22 |
| Measured value display- | 14 |
| Measured value old probe | 24 |
| Measurement range | 42 |
| Measurement range MTI | 44 |
| Measuring circuit voltage/current MTI | 44 |
| Measuring circuits, quantity, Menu | 16 |
| Measuring range | 11, 25 |
| Measuring range, end point | 25 |
| Measuring range, Menu | 17 |
| Measuring range, starting point | 25 |
| Measuring span- | 24 |
| Measuring span acceptance, push button | 24 |
| Menu Activation code | 16 |
| Menu Active dataset, protocol | 17 |
| Menu Archive | 17 |
| Menu Calculation parameters | 17 |
| Menu Code | 30, 31 |
| Menu Code parameter | 16, 17, 18 |
| Menu Controller function | 17 |
| Menu description, - | 19 |
| Menu Limit values | 17 |
| Menu parameter settings | 15 |
| Messwertverarbeitung | 12 |
| Monitoring | 42 |
| Monitoring frequency MTI | 44 |
| Mounting | 44 |
| MTI | 44 |
| MTI technical data | 44 |
| Multipoint connector, 32 poles | 39 |

N

| | |
|--|----|
| NAMUR EN53 | 22 |
| Nominal data of supply voltage MTI | 44 |
| Number of measuring circuits | 23 |

O

| | |
|---|-------------------|
| Oil detection, with a float | 31 |
| Oil in Water, detection- | 30 |
| OK button (key –OK-) | 3, 13, 15 |
| Old probe, measured value | 24 |
| Operation / Display | 42 |
| Operation/display MTI | 44 |
| Opto-electronic coupler | 6, 11, 26, 27, 40 |
| Opto-electronic coupler, de-energized | 27 |
| Opto-electronic coupler, define security settings | 27 |
| Opto-electronic coupler, switched on | 27 |

P

| | |
|--|--------|
| Parameter | 13 |
| Parameter set, load | 21 |
| Parameter set, store- | 21 |
| Parameter settings, Menu | 15 |
| Parameter values | 13 |
| Parameterization | 13 |
| Password | 19 |
| Password, key-in, change | 20 |
| Password, modify | 20 |
| Password, modify, Menu | 16 |
| Passwort input | 15 |
| PC software | 13 |
| Plant, Hazardous Area | 38 |
| Power Input | 42 |
| Printed circuit board | 40 |
| Probe already soiled with products, (settings) | 30, 31 |
| Probe factor | 24 |
| Probe type 1 / 2 | 23 |
| Probes, without reference electrode | 32 |
| Product | 11 |
| Program messages | 3 |
| Program structure with parameters | 16 |
| Programmable error level mA output | 28 |
| protection housing MTI | 44 |
| Pulses | 11 |
| Purpose | 42 |

R

| | |
|--|----|
| Rack, 19 | 30 |
| Rack, Monorack | 30 |
| Radio equipment and transmitter- | 37 |
| Relays outputs | 42 |
| Resolution MTI | 44 |

S

| | |
|---|------------|
| Safety level switch | 12 |
| Second measuring circuit, activation | 22 |
| SEE 99 ATEX 2469 | 44 |
| Selec measuring circuit | 25 |
| Select language | 13 |
| Select measuring circuit | 23, 25, 27 |
| Serial No 1 / 2 | 23 |
| Serial number and system verify, Menu | 16 |
| Serial number system verify | 22 |
| Service parameter basics, Menu | 17 |
| Settings, basic, Menu | 16 |
| Settings, if probe already soiled with products | 30, 31, 32 |

| | |
|---|--------|
| Setup | 6 |
| Signal filter- | 25 |
| Signal line short circuit | 42 |
| Signal settings | 23 |
| Signal settings, Menu | 16 |
| Signal transmission | 42 |
| Simulation of mA output | 27 |
| Software | 8 |
| Software (Display) | 22 |
| Software, activation | 22 |
| Software, codes | 9 |
| Software, dutiable | 22 |
| Software, functions | 22 |
| Software, marking | 22 |
| Software, operating | 10 |
| Software, packages | 22 |
| Software, PC | 13 |
| Software, release (Display) | 22 |
| Software, standard | 9 |
| Software, versions | 10, 16 |
| Soiled and uncleaned probes, settings | 32 |
| Standard measuring range for bar probes MTI | 44 |
| Statische Messwertverarbeitung | 12 |
| Storage temperature | 42 |
| Storage temperature MTI | 44 |
| Store parameter set | 21 |
| Structure Data input- | 13 |
| Surface oil, detection | 31 |
| Switch on current | 42 |
| Switching hysteresis | 42 |
| Symbols | 3 |

T

| | |
|---|--------------|
| Technical Data | 42 |
| Technical error | 28 |
| Technical error level | 39 |
| Technical error, Measured value 1 overflow | 36 |
| Technical error, Measured value 1 underflow | 35 |
| Teflon coated | 44 |
| Test and certification | 42 |
| Test and certification MTI | 44 |
| Test functions | 27 |
| Test functions, Menu | 17 |
| Text input | 13 |
| Time, drop off or on raise delay | 26 |
| Time/Date | 20 |
| Time/Date, Menu | 16 |
| Transmission signal MTI | 44 |
| Type code | 8, 9, 10, 16 |
| Type code, (Display) | 23 |
| Types, of hardware | 8, 22 |

U

| | |
|--------------------------------|---|
| Using this manual | 3 |
|--------------------------------|---|

V

| | |
|-------------------------|------------|
| Version, 24 V | 39 |
| Version, manual | ii |
| Version, MTI | 44 |
| Version, software | 10, 16, 22 |

W

| | |
|--------------------------------|----|
| Warranty claims | 7 |
| Waste disposal of... .. | 7 |
| Water in Oil, detection | 30 |
| Weight | 42 |
| Weight of electronic MTI | 44 |
| Wiring diagram | 38 |

Z

| | |
|--|----|
| Zero point acceptance, push button | 24 |
| Zero point input, manual | 24 |
| Zero point MeV (display) | 32 |
| Zero point, accept actual | 30 |

List of tables:

| | | |
|----------|--|----|
| Chart 1 | Symbol description | 3 |
| Chart 2 | Key functions | 13 |
| Chart 3 | Display | 13 |
| Chart 4 | Program structure | 18 |
| Chart 5 | Fail Safe settings | 27 |
| Chart 6 | Commissioning of water detection | 30 |
| Chart 7 | Commissioning of oil detection | 30 |
| Chart 8 | Commissioning of oil layer detection | 31 |
| Chart 9 | Commissioning of foam detection | 31 |
| Chart 10 | Electronic calibration operating sequences | 32 |

List of pictures:

| | | |
|--------|---|----|
| Pic. 1 | mipromex® | 8 |
| Pic. 2 | static measure processing mode | 12 |
| Pic. 3 | dynamic processing mode | 12 |
| Pic. 2 | Wiring diagram | 38 |
| Pic. 3 | FI 32 female multipoint connector to MAT 4190 | 39 |
| Pic. 4 | Connection print to mipromex | 40 |
| Pic. 5 | Earthing principle | 41 |
| Pic. 6 | Measuring electronic | 43 |

Notes: